



TECHNICAL SERVICE BULLETIN

SUBJECT:

WINDOW FOGGING

NO. TSB-96-42A-007

DATE March, 1996

MODEL All models

CIRCULATE TO:



SERVICE ADVISOR



GENERAL MANAGER



SERVICE MANAGER



PARTS MANAGER



WARRANTY PROCESSOR



TECHNICIAN



SALES MANAGER

PURPOSE

Some vehicles may experience interior window or windshield film build-up ("fogging"). This condition is caused by vinyl interior trim material releasing chemical agents that adhere to the glass.

Several aftermarket products are available for removing film build-up from glass. The following products have been tested by MMSA and found to be effective. Repeated applications may be necessary.

- Oily Film Remover by The Wax Shop (part number WS34-020) comes in a 20 ounce spray bottle and can be ordered from Basics Etc. at 800-333-1135 (or fax a purchase order to 909-699-9248). The product can also be purchased at some Pep Boys retail auto parts stores. Follow the aftermarket manufacturer's application instructions.
- P21s wipes are available in a case of 24 packages. Each package contains four wipes in individually sealed pouches. P21s wipes are available by COD only. To order, call Brookside Import Specialties at 800-215-9442. Follow the aftermarket manufacturer's application instructions.

NOTE: This product information is provided to Mitsubishi dealers to enhance customer satisfaction. These products do not carry an MMSA warranty or guarantee.

AFFECTED VEHICLES

All Mitsubishi models

Produced by the MMSA Technical Information Department.

Copyright 1996
Mitsubishi Motor Sales of America, Inc.
All rights reserved

.....
Index * 048230
.....